



# Flat-Lock Soldered Copper Roofing

Barry Smith

For a roof pitch less than  $\frac{3}{12}$ , a solid membrane roof of some sort is needed. One long-term solution is a flat-lock soldered copper roof. This can be done using just a few hand tools<sup>1</sup>, but the time required can be greatly reduced with the proper sheet metal equipment.<sup>2</sup>






The basic component of this style roof is the roofing pan, which is a rectangle typically measuring 18" by 24," though I have seen old roofs with pans smaller or larger than this. The largest that I remember were 24" by 30." Multiple small pans are used, instead of fewer, larger ones, so that thermal expansion and contraction can be absorbed by each pan, instead of accumulating and concentrating in just a few areas, where it could tear the metal apart. If the roof area exceeds 30' in any direction, then an *expansion joint is needed*. I always have rolls of 18" 20 oz. cold rolled copper around for flashing purposes, so 18" x 24" stock is what I start with.

The pans will have  $\frac{3}{4}$ " folds around the perimeter, 2 turned up, and 2 turned down, as shown at right. Again, this could be less ( $\frac{1}{2}$ " or more (1")), but I find  $\frac{3}{4}$ " to be a nice width, in that there is some extra room for adjustment, when fitting them together without losing too much pan size. The corners have to be trimmed off first to allow the sides to be bent properly (Figure 2). At  $\frac{3}{4}$ ", scribe two lines in one corner, and draw a 45 degree line so that the intersection made by the two  $\frac{3}{4}$ " lines is cut off, leaving a  $\frac{3}{16}$ " wide corner. When the edges get folded, this will leave a  $\frac{3}{16}$ " wide crack which is called a butt (I'll pretend I don't hear that giggling!) This can vary, but if too thin, the pans won't fit easily together, and if too wide, there will be a big hole that needs to be filled with solder.

So the pans are cut to size, and the corners are cut off. Now they can be "pre-tinned,"<sup>3</sup> which means applying a stripe of solder around the perimeter of the pans, on both sides. Because we are making  $\frac{3}{4}$ " seams, the stripe will be twice that, or  $1\frac{1}{2}$ ". Though pre-tinning is widely recommended, it isn't required. It does reduce the chances of having voids in the solder joints after the pans are assembled and soldered, but an experienced mechanic can apply all of the solder at one time, and be confident that the joints are good. Pre-tinning is a form of "idiot proofing," which, when you are a beginner, is a good thing!

Now, the edges can be folded (2 up, 2 down), at about a 130 degree angle. Your pans are ready for the roof.

The roof sheeting should be solid 1" boards, not plywood, and covered with 30 lb. felt. Install rosin paper, so that the copper doesn't come into contact with the felt. This will keep the felt from melting into the solder joints, and provides a slippery



surface as the copper expands and contracts.

Install the drip edge (Figure 3). Snap a chalk line  $22\frac{1}{2}$ " from the outside of the drip edge and begin installing the pans in the staggered pattern shown above using copper cleats measuring roughly  $1\frac{1}{2}$ " by 3". Use the chalkline as a guide to keep everything straight, but don't worry if the pans aren't lining up perfectly. The cleats can be nailed with 1 or 2 nails (I've seen both recommended), and then folded over the nail. There can be two or three cleats on the long side.

The pans should ideally lay on the roof, so that water runs out of the joint, not into it. This isn't required however, since the joint will soon be filled with solder, and sometimes,

Photos this page and facing page by Joseph Jenkins

Continued On Next Page ➡

